

# AERIAL ROOF REPORT

Your Company Name

Phone: 978-321-5424

Email: info@yourcompany.com

YOUR LOGO

## Customer Information

13 July 2020

1916 Danniston Crescent, Manchester MA 01944

Table of Contents	Page
Report Summary	2
Lengths Measurements & Total Quantities	3
Area Measurements & Waste Factor Table	4
Pitch Measurements & Quantities Breakdown	5




# MyRoofReport




Copyright © Offsite Roof Reports, LLC – All Rights Reserved  
[www.MyRoofReport.com](http://www.MyRoofReport.com) | (339)226-6603



Total Lengths	
<b>Total Squares</b>	<b>23.84</b>
Ridge Length	79'
Eave Length	159'
Hip Length	37'
Valley Lengths	70'
Transition Length	0'
Step Flashing	22'
Apron Flashing	45'



Total Quantities	
Total Squares	23.84
-Waste Factor-	
10%	26.22
15%	27.41
20%	28.60
25%	29.80
Ridge Length	79'
Eave Length	159'
Hip Length	37'
Valley Lengths	70'
Transition Length	0'
Rake/ Gable Length	126'
Step Flashing	22'
Apron Flashing	45'
Perimeter (Eave + Gable)	286'



	4:12	6:12
<b>Total Squares</b>	7.43	16.40
<b>Ridge Length (ft)</b>	10'	69'
<b>Eave Length (ft)</b>	80'	79'
<b>Hip Length (ft)</b>	37'	0'
<b>Valley Length (ft)</b>	16'	55'
<b>Gable Length (ft)</b>	10'	117'
<b>Step Flashing (ft)</b>	17'	5'
<b>Apron Flashing (ft)</b>	32'	13'